

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

Mine Name: Bonneville Plant / Reilly Wendover

Inspector(s): Leslie Heppler

Operator Name: Intrepid Potash – Wendover LLC

JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program

Date: June 1, 2009

Reviewed:	LK_

Permit Number: M0450002 Inspection Date: 05/26/2009

Time: 9:00 am

Other Participants: Brett Gregory & Vicky Dyson		Mine Status: Active		
	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds	\boxtimes	\boxtimes	
2.	Public Safety (shafts, adits, trash, signs, highwalls)	\boxtimes	\boxtimes	
3.	Protection of Drainages / Erosion Control	\boxtimes	\boxtimes	
4.	Deleterious Material	\boxtimes	\boxtimes	
5.	Roads (maintenance, surfacing, dust control, safety)	\boxtimes	\boxtimes	
6.	Concurrent Reclamation			
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8.	Water Impoundments	\boxtimes	\boxtimes	
9.	Soils			
10	. Re-vegetation			
11	. Air Quality	П		

Bond Amount: \$49,100 **Bond Renewal Date** 07/18/1998 **Permit fee**: \$1000 due - invoice sent out 06/20/2009

Purpose of Inspection: Routine Annual Inspection, last inspection date 07/01/2004

<u>Inspection Summary</u>: There is currently a CD Bond in the amount of \$49,100. A new NOI has been completed with a new surety has been calculated, but has not yet been received. The ponds were inspected on this inspection, next year the process facilities will be inspected. The ponds, canals, dikes, ditches and roads were all maintained in good shape, no erosion problems or deleterious material or trash was noted.

<u>Conclusions and Recommendations</u>: The bond renewal date is past due for escalation. The operator should submit the new bond within 30 days (August 12, 2009)

Inspector's Signature

12. Other

LA:vs

cc: Rick York

BLM - <u>stan_perkes@blm.gov</u> SITLA-<u>wStokes@utah.gov</u>

O:\M045-Tooele\M0450002-bonneville plant-reilly\inspections\insp-05262009.doc





Transfer pump









Harvest pond

